Wednesday, 3/14/2007 12:25:24 PM User: Kim Johnston **Process Sheet** : LANYARD ASSEMBLY **Drawing Name** : CU-DAR001 Dart Helicopters Services Customer Job Number **Estimate Number** : 11493 : MA : D26906 Part Number P.O. Number D2690 REV. B2 S.O. No. : 41A **Drawing Number** : 3/14/2007 This Issue : N/A Project Number Prsht Rev. : NC : SMALL /MED FAB : B2 Type **Drawing Revision** First Issue : HIA : 29390 Material **Previous Run** Each : 3/21/2007 Qty: 10 Um: **Due Date** Written By Checked & Approved By Reformat; Incorporated D2690-X : Est: 03.04.04 Comment J/RF **Additional Product** Job Number: Description: Seq. #: Machine Or Operation: Loop Sleeve **CBL460** 1.0 Comment: Qty.: 2.0000 Each(s)/Unit Total: 20.0000 Each(s) Loop Sleeve **Qty Part Number** Description 2 CBL-460 Loop Sleeve CBL1240 2.0 10.0000 f(s) Comment: Qty.: 1.0000 f(s)/Unit Total: Cable Part Number Description Batch Qty D2690-6 + 2.5" CBL-1240 Cable Comment: SMALL & MEDIUM FAB RESOURCE 1 Assemble as per Dwg D2690 Identify as D2690-6 4.0 QC5 WORK TO CURRENT STEP. Comment: INSPECT PACKAGING RESOURCE #1 PACKAGING 1 5.0 Comment: PACKAGING RESOURCE #1 Identify and Stock Location:

Dart A	Aeros	pace	Ltd
--------	-------	------	-----

W /O:			WORK ORDER C	R CHANGES							
DATE	STEP	PROCEDURE CHANGE		PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		^									
		,									
				<u> </u>	(2)						

Part No: Da 690-6 PAR #: MA Fault Category: Prod Fas. Ass! NCR: Yes No DQA:

Date: 07/04/04

QA: N/C Closed: Date: 07.04.09

NCR:	3110	V	WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC	l=i4ial	Corrective Action		n B Sign &	Verification	Approval	Approval
			Section A Initial Chief Eng		Action Description Chief Eng		Section C	Chief Eng	QC Inspector
	(3) 12690-6 was		Scrap 5 A	2690-6		M		21
162	2.0	under tol. by .100" to	· 150"/				07/04/02	//	07/04/02
न्याज्यकि	,		PSICULZ	-		FForla	07/04/02	POSINZ	
		when removing protective	e					, 4	
								:	
	-		·						
								(*)	
	t			,					77
									z.

NOTE: Date & initial all entries

Date:

Wednesday, 3/14/2007 12:25:25 PM

Usêr:

Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LANYARD ASSEMBLY

Job Number: 31191

Part Number: D26906

Job Number:

Seq. #:

Machine Or Operation:

Description:

6.0

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



U 8404.04

Dart Aerospace

W/O:			WORK ORDER C	HANGES	ANGES						
DATE	STEP	PR	ROCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
		1									
-											
Part No) :	 PAR #:	Fault Category:	NC	R: Yes	No DQ	A:	Date:			

QA: N/C Closed: ____ Date: ____

NCR:			W	ORK OR	DER NON-CONFO	RMANCE	(NCR)			
		Description	of NC		Corrective Action	Section B		Verification	A	Annroval
DATE	STEP	Section	A	Initial Chief Eng	Action Descri	otion	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
								1		
			!				1			


NOTE: Date & initial all entries



	DESIGN DRAWN BY			DART AEROSPACE LTD VICTORIA INTERNATIONAL AIRPORT, CANADA
	CHECH	(ED,/	APPROVED	DRAWING NO. REV. B
	$ \mathcal{D} $	nog	BW	D2690 SHEET 1 OF 1
	DATE			TITLE SCALE
100000	97.1	0.02		LANYARD ASSEMBLY NTS
	Α		97.07.03	NEW ISSUE
	Э		97 10 02	REVISED NOTE FOR ADDITIONAL LENGTH



DATE		TITLE SCALE
97.1	10.02	LANYARD ASSEMBLY NTS
Α	97.07.03	NEW ISSUE
В	97.10.02	REVISED NOTE FOR ADDITIONAL LENGTH
Bı	AF CP 01.08.20	ADD NOTE TO REMOVE 2.25" OF SLEEVE
BZ	# 04.06.24	ADDED TOLERANCE



X = LENGTH IN INCHES

CUT CABLE 2.50* INCHES LONGER THAN 'X' LENGTH. NOTE:

FOLD ENDS TIGHT TO 'X' LENGTH AND CRIMP WITH SLEEVE AT END OF LOOSE END OF CABLE WITH

CBL-705 CRIMPING TOOL.

SHOP COPY RETURN TO

*ADDITIONAL LENGTH MAY BE NECESSARY IN

ENGINEERING

SOME APPLICATIONS. CUT AS REQUIRED.

UNCONTROLLED COPY

IN SOME CASES, END HAS TO BE CRIMPED AFTERWITHOUT NOTICE NOTE:

ASSEMBLY WITH ATTACHING PARTS.

DEO's Copyright 1997 by DART AEROSPACE LTD

